Volvo Penta of the Americas 1300 Volvo Penta Drive Chesapeake, Virginia 23320-9810

3863460

3862704

3860965

Parts	Bu	letin
Group	Number	Version
P-37-2	2	01

Fuse/Relay box replaced

Models: gas 4.3/S.0/S.7/8.1L EFI

Distribution:	Parts	Date: 07-2006	Binder: Parts	Replaces: N/A	

50745

The following fuse/relay box part numbers have been replaced by service kit **3808318**;

3863460 3862704 3860965

These boxes, shown at left, were used on the following gas EFI engines;

4.3/5.0/5.71 spec numbers between 3869132 and 3869277.

8.11 spec numbers between 3869087 and 3869292.

Kit **3808318** contains the latest version of the fuse/relay box **plus** isolator bushings for mounting the box to the engine.

The isolators reduce vibration to the box, lengthening the service life of the box. Mounting instructions are included in the kit.

Part numbers for the isolators and hardware are shown in the illustration.