## **Volvo Penta**

## I have a 3.0 Volvo Penta engine on my 18.5 stingray. The trim cylinder is leaking fluid from a seal. I can't seem to find a rebuild kit or seals. Can you help?

If your drive is an SX drive then I can supply a good rebuild kit that I designed and we have

been selling for years.

However, if it is an SX-A drive then the only option is to replace the

trim cylinder (which we can also supply).

Unique solution ID: #1221 Author: Dan Bettencourt Last update: 2020-06-29 13:33