



2213

| Parts List | | | | | | |
|------------|-------|-----------|--------------------------------|-----|---------------------------------|----------|
| Ref | Class | Part | Description | Qty | Comment | Footnote |
| 1 | | 98869A11 | ELECTRODE ASSEMBLY | 1 | (Use Without Quick Connectors) | |
| 1 | | 98869A16 | ELECTRODE ASSEMBLY | 1 | (With Quick Connectors) SN# 0M6 | |
| 2 | 84 | 865181A01 | HARNES ASSEMBLY, Mercathod | 1 | | |
| 3 | 13 | 26992 | LOCKWASHER, (.250) | 2 | | |
| 4 | 12 | 29245 | WASHER, (.281 x .500 x .060) | 2 | | |
| 5 | 56 | 42600A 3 | CONTROLLER ASSEMBLY | 1 | | |
| 6 | 11 | 68219 | NUT, (#10-32) | 4 | | |
| 7 | 84 | 88543A 3 | CABLE ASSEMBLY | 1 | | |
| 8 | 10 | 62568 | SCREW, (#10-16 x .375) | 1 | | |
| 9 | 10 | 40105 16 | SCREW, (M5 x 16) | 2 | | |
| 10 | 88 | 79091 | FUSE, (20 Ampere) | 1 | | |
| 11 | 84 | 95084A 9 | CABLE ASSEMBLY, (91.00 Inches) | 1 | | |
| 11 | 84 | 95084A10 | CABLE ASSEMBLY, (5.00 Inches) | 1 | | |
| 12 | 10 | 69067 | SCREW, (.25-20 X 1.375) | 2 | | |