



2213

Parts List						
Ref	Class	Part	Description	Qty	Comment	Footnote
1		98869A11	ELECTRODE ASSEMBLY	1	(Use Without Quick Connectors)	
1		98869A16	ELECTRODE ASSEMBLY	1	(With Quick Connectors) SN# 0M615000	22
2	84	865181A01	HARNES ASSEMBLY, Mercathod	1		
3	13	26992	LOCKWASHER, (.250)	2		
4	12	29245	WASHER, (.281 x .500 x .060)	2		
5	56	42600A 3	CONTROLLER ASSEMBLY	1		
6	11	68219	NUT, (#10-32)	4		
7	84	88543A 3	CABLE ASSEMBLY	1		
8	10	62568	SCREW, (#10-16 x .375)	1		
9	10	40105 16	SCREW, (M5 x 16)	2		
10	88	79091	FUSE, (20 Ampere)	1		
11	84	95084A9	CABLE ASSEMBLY, (91.00 Inches)	1		
11	84	95084A10	CABLE ASSEMBLY, (5.00 Inches)	1		
12	10	69067	SCREW, (.25-20 X 1.375)	2		