



5716

TD100ARC

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1	843536	1	Box		
2	843562	1	Attaching plate		
3	940159	3	Screw		
4	941907	3	Spring washer		
5	821539	3	Spacer sleeve		
6	1228599	4	Rubber cushion		MO-XXXX/39532
7	955781	8	Nut		MO-XXXX/39532
8	941906	8	Spring washer		MO-XXXX/39532
9	845513	4	Absorber		MOXXXX/39533-
10	955782	8	Nut		MOXXXX/39533-
11	941907	8	Spring washer		MOXXXX/39533-
12	955295	4	Screw		MOXXXX/39533-
13	843094	2	Flange		
14	843578	2	Gasket		
15	956093	8	Screw		
16	881193	2	Cable union		
17	822327	2	Cable union		
18	843903	X	Plug		
19	843577	1	Flange		
20	843579	1	Gasket		
21	956114	4	Screw		
22	955782	4	Nut		
23	941907	4	Spring washer		
24	955781	8	Nut		
25	941906	8	Spring washer		
26	843544	1			EARLY TYPE
27	956074	4	Screw		EARLY TYPE
28	941905	4	Spring washer		EARLY TYPE
29	924045	6	Stud		LATE TYPE
30		6	SPACER WASHER		NO LONGER USED
31	843375	1	Circuit board		
32	963104	6	Nut		
33	962673	12	Washer		
34		1	DAMPING ELEMENT		MOXXXX/39533-
35	1504951	16	Relay		
36	842987	1	Voltage sensor		
37	843910	1	Race gard		
38	944077	4	Housing		
39			CABLES		FOR CABLE AREA 0,75-2,0 SQMM.
				030-1000	