
26 Water Pump

, KAMD300-A



## , KAMD300-A

REF	PART NO.	QTY		SEE SEC.	NOTES
1	3583096	1	Water pump		Replaced by 1 pc 3809412, coolant pump, 1 pc 3588384, pulley and 4
	0000440		10.		pcs 947760, flange screw., Repl by 3809412
	3809412	1			
2	3803869 (184861)	1			Obsolete part, Included in overhaul kit.
3	(3588402)	1	Hub		Obsolete part
4	3583087	1	Impeller, with shaft		Included in overhaul kit.
5	914462	1	Snap ring		Included in overhaul kit.
6	479977	1			Included in eventual inc.
7	1660609	1	Ball bearing		Included in overhaul kit.
8	1676432	1			Included in overhaul kit.
9	3580971		Pulley		For multi-V-belt.
10	877385	1	-	5105	
11	859027	1	Gasket		Included in overhaul kit.
11A	947760	6	Flange screw		
12	3582167	1			Included in service kit.
12A	3582168	1	Gear		Included in service kit.
13	3582189	1	1 - 1		Included in service kit.
13A	982331	1			Included in service kit.
14	3582324	1	,	-	Included in service kit.
15	976945	1	Washer		Included in service kit.
16	971095	1	Flange nut	-	Included in service kit.
17	3582677	1	Nut		Included in service kit.
18	3582424	1	Drive belt		Lloot evolunger evolungen tenk weter numn
19 20	3581099 943478	1			Heat exchanger-expansion tank-water pump.
21	860388	1	<u> </u>		
22	860454	1			
23	947760	4			
24	977542	1	V-belt		
25	877180	1	Service kit		
	077.00		• Bulletin 44-48	44-48-EN	Belt tensioner Upgrade Kit for D32, 42WJ, 42, 44
					, , , , , , , , , , , , , , , , , , ,
				1	

7738870-26-5111 21142 Upd:2012-02-13