

Upd: 08 JUN 2006 21144 7738870 - 26 - 5086B

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1	3580784	1	Circulation pump		REPL BY 3809412. Replaced by 1 pc 3809412, coolant pump, 1 pc
					3588385, pulley and 4 pcs 947760, flange screw.
1	3809412	1			
	3803869	1			Exchange unit
2	184861	1			Included in overhaul kit.
3	3588402	1	• Hub		
4	3583087	1			Included in overhaul kit. Included in overhaul kit.
5	914462	1	3		included in overnaul kit.
<u>6</u> 7	479977 1660609	1			Included in overhaul kit.
8	1676432	1			Included in overhaul kit.
0	1070432	1	- Sealing fing		included in overriadi kit.
9	3588385	1	Pulley		LATE TYPE. For multi-V-belt.
	3300303	'	1 uney		LATE THE ETO Multi-V-belt.
10	876794	1	Repair kit	3434	
11	859027	1	Gasket	0 10 1	Included in overhaul kit.
11A	947760	6			The same of the sa
12	3582167	1			Included in service kit.
12A	3582168	1	Gear		Included in service kit.
13	3582189	1	Spacer		Included in service kit.
13A	982331	1	Square neck screw		Included in service kit.
14	3582324	1	Tension pulley		Included in service kit.
15	976945	1			Included in service kit.
16	971095	1			Included in service kit.
17	3582677	1			Included in service kit.
18	3582424	1	Drive belt		
19		1	Screw		SEE GROUP 22
20	846780	1	Bracket		
21	955894	1			
22	952635	1	Clamp		
23	955893	1	Washer		(000055)
24	948746	1	Flange screw		(968855)
25	3581099	1	Hose		Heat exchanger-expansion tank-water pump.
26	943478	1	Clamp		
27	860388	1	Drive belt		
28	860454	1	Pulley		
29	947760	4			
30	977542	1			
31	877180	1		3434	
			Bulletin 44-48	44-48-EN	Belt tensioner Upgrade Kit for D32, 42WJ, 42, 42, 44