

REF	PART NO.	OTV	DESCRIPTION	SEE SEC.	NOTES
\EF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
	3580972	1	Motor numn		DEDI DV 2000412 Paplaced by 4 no 2000442 content name 4 no
1	3580972	1	Water pump		REPL BY 3809412. Replaced by 1 pc 3809412, coolant pump, 1 pc
					3588384, pulley and 4 pcs 947760, flange screw.
	3809412	1			
	3803869	1			Exchange unit
2	184861	1	Ball bearing		Included in overhaul kit.
3	3588402	1			
4	3583087	1			Included in overhaul kit.
5	914462	1	Lock ring		Included in overhaul kit.
6	479977	1			moraded in overnaur kit.
U	4/99//	I	- Flug		
	4070400		O line as aire as		Included in overhaul kit.
8	1676432	1			
<u> </u>	3580971	1	• Pulley		EARLY TYPE
9	3588384	1			LATE TYPE. For multi-V-belt.
10	876794	1	Repair kit	3434	
11	859027	1	Gasket		Included in overhaul kit.
11A	947760	6			
12	3582167	1	Bracket		Included in service kit.
12A	3582168	1			Included in service kit.
13	3582189	1			Included in service kit.
13A	982331	1	Square neck screw		Included in service kit.
14	3582324	1			Included in service kit.
15	976945	1			Included in service kit.
16	971095	1			Included in service kit.
17	3582677	1	Nut		Included in service kit.
18	3582424	1	Drive belt		
25	3581099	1	Hose		Heat exchanger-expansion tank-water pump.
26	943478	1	Clamp		
27	860388	1			
28	860454	1			
29	947760	4			
30	977542	1			
				0.40.4	
31	877180	1		3434	
			Bulletin 44-48	44-48-EN	Belt tensioner Upgrade Kit for D32, 42WJ, 42, 42, 44

7738870 - 26 - 5086C 21144 Upd: 08 JUN 2006