

REF	PART NO.	QTY	DESCRIPTION	NOTES
1			Turbocharger	Replaced by 3826985.
		-		
2		1		
3			Turbine housing	
4			Segment Serow	Included in renair kit 2020744
5 6			Screw Rotor unit	Included in repair kit 3830711. REPL BY 863771
0		ı	· Rotor unit	REFL DT 003//T
7		1	· · Turbine rotor	
·				
8		2	· · Washer	
9		1	· · Bushing	
10		1	· · Oil deflector ring	
11		1	· · Sealing ring	
12		1	· · Compressor wheel	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
13		1	· · Nut	Included in repair kit 3830711.
14		1	· · Piston ring	Included in repair kit 3830711.
15		4	· · Screw	Included in repair kit 3630711. Included in repair kit 3830711.
16			· · Washer	Included in repair kit 3830711.
17	849687		· · O-ring	Included in repair kit 3630711.
18	0.000.		· · Cover	
19			· · O-ring	Included in repair kit 3830711.
20		1	· · Oil deflector	Included in repair kit 3830711.
21			· · Thrust bearing	Included in repair kit 3830711.
22			· · Bushing	Included in repair kit 3830711.
23			Lock ring	Included in repair kit 3830711.
24		1		
25		1	· · Shield	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
26 27		4	· · Piston ring	Included in repair kit 3830711.
28			- Screw - Segment	Included in repair kit 3830711. Included in repair kit 3830711.
29	863765		Repair kit	ilicidded iir fepail kit 30307 FT.
25	876804	1		For mounting of the turbocharger. Bring also 4 ea sealing ring 3825197
	0.000.	•	Cusinet IIII	gg o. a g ogggg

7745600 - 25 - 4546 18019 Upd: 21 NOV 2005