

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	3826913	1	Turbocharger	
2		1	Turbine housing	
3		1		
4			Rotor unit	
5		1		
6			· · Shield	
7		2		Included in repair kit 3830711.
8		4	· · Lock ring	Included in repair kit 3830711.
9		1	· · Piston ring	Included in repair kit 3830711.
10			· · Thrust bearing	Included in repair kit 3830711.
11 12		1		Included in repair kit 3830711.
13			Compressor wheel	
14		1		
15			· · Sleeve	
16			· · Bushing	
17			· · Seal	
18		1	· · Nut	Included in repair kit 3830711.
19		1	· · Pressure plate	
20	845829	4	· · Screw	Included in repair kit 3830711.
21			· · Piston ring	Included in repair kit 3830711.
22		1		Included in repair kit 3830711.
23	955270	6	· Screw	 Included in repair kit 3830711.
0.4			Mark an	la alcala dia nanasia bit 0000744
24 25	955269	3 6		Included in repair kit 3830711.
25	955269	ь	• Screw	Included in repair kit 3830711.
26		3	Segment	Included in repair kit 3830711.
27	847643	1	O-ring	Included in repair kit 3830711.
28	3828598	1	· Valve, kit	included in repair kit 0000711.
	0020000		varo, ni	
28A		1	· · Valve	
29	864778	1		
30	942001		· · Screw	
31	947620		· · Gasket	
32	74033		· · Hollow screw	
33	3825126		• Feed line	
34	866286	1	Repair kit	(849590)

7740790 - 25 - 3515 17561 Upd: 30 MAR 2006