

Volvo Penta

MD2030B Piston Kit Question

Hello,

I have a customer with a MD2030B who purchased a Standard Piston kit part #876694. Can we confirm that the new piston is supposed to have the flat surface because it is clearly different from the old piston. Please see attached pic.

Thanks,

Hello,

the answer from Volvo's engineering department is that yes, the piston is correct.

Thanks,

Unique solution ID: #1124

Author:

Last update: 2015-03-05 18:14