



2213

| Parts List |       |           |                                |     |         |          |
|------------|-------|-----------|--------------------------------|-----|---------|----------|
| Ref        | Class | Part      | Description                    | Qty | Comment | Footnote |
| 1          |       | 98869A17  | ELECTRODE ASSEMBLY, With Qi    | 1   |         |          |
| 2          | 84    | 865181A01 | HARNESS ASSEMBLY, Mercath      | 1   |         |          |
| 3          | 13    | 26992     | LOCKWASHER, (.250)             | 2   |         |          |
| 4          | 12    | 29245     | WASHER, (.281 x .500 x .060)   | 2   |         |          |
| 5          | 56    | 42600A 3  | CONTROLLER ASSEMBLY            | 1   |         |          |
| 6          | 11    | 68219     | NUT, (#10-32)                  | 4   |         |          |
| 7          | 84    | 88543A 3  | CABLE ASSEMBLY                 | 1   |         |          |
| 8          | 10    | 62568     | SCREW, (#10-16 x .375)         | 1   |         |          |
| 9          | 10    | 40105 16  | SCREW, (M5 x 16)               | 2   |         |          |
| 10         | 88    | 79091     | FUSE, 20 Ampere                | 1   |         |          |
| 11         | 84    | 95084A 9  | CABLE ASSEMBLY, (91.00 Inches) | 1   |         |          |
| 11         | 84    | 95084A10  | CABLE ASSEMBLY, (5.00 Inches)  | 1   |         |          |
| 12         | 10    | 45862     | SCREW, (#10-32 x .875)         | 1   |         |          |