



| Parts List |       |           |                        |     |         |          |
|------------|-------|-----------|------------------------|-----|---------|----------|
| Ref        | Class | Part      | Description            | Qty | Comment | Footnote |
| 1          |       | 881247A 1 | ALTERNATOR             | 1   |         |          |
| 2          | 24    | 852374 2  | SPRING                 | 1   |         |          |
| 3          |       | 856815T 2 | ARM TENSIONER ASSEMBLY | 1   |         |          |
| 4          | 12    | 40023 20  | WASHER                 | 2   |         |          |
| 5          | 23    | 856894 1  | BUSHING                | 1   |         |          |
| 6          | 16    | 856900    | STUD, (M10 x 85)       | 1   |         |          |
| 7          | 11    | 826292    | NUT, (M10)             | 1   |         |          |
| 8          |       | 852385A 2 | PULLEY ASSEMBLY        | 1   |         |          |
| 9          | 10    | 40108 35  | SCREW, (M10 x 35)      | 1   |         |          |
| 10         | 57    | 828507Q 5 | BELT                   | 1   |         |          |
| 11         | 283   | 859619T 1 | FLYWHEEL               | 1   |         |          |
| 12         | 11    | 42979     | NUT, (M16)             | 1   |         |          |
| 13         | 12    | 68229     | WASHER                 | 1   |         |          |
| 14         | 19    | 45907     | PLUG, (Yellow)         | 1   |         |          |
| 15         | 11    | 40138 6   | NUT, (M6)              | 1   |         |          |
| 16         | 84    | 856583A 5 | CABLE ASSEMBLY         | 1   |         |          |
| 17         | 12    | 40023 19  | WASHER                 | 1   |         |          |
| 18         | 10    | 821301 50 | SCREW, (M10 x 50)      | 2   |         |          |
| 19         | 10    | 821300 12 | SCREW, (M6 x 12)       | 1   |         |          |