

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	3826913	1		
			<del>-</del>	
3		1		
4			Rotor unit	
5		1		
6		1	· · Shield	
7		2	· · Bushing	Included in repair kit 3830711.
8			· · Lock ring	Included in repair kit 3830711.
9		1		Included in repair kit 3830711. Included in repair kit 3830711.
11		1		Included in repair kit 3830711.
12		1		incided in repair kit 36307 11.
13		1	· · Compressor wheel	
14		1		
15		1		
16		1		
17 18		1	· · Seal · · Nut	Included in repair kit 3830711.
19		1		included in repair kit 3030711.
20	845829		· · Screw	Included in repair kit 3830711.
21		2	· · Piston ring	Included in repair kit 3830711.
22		1	· · O-ring	Included in repair kit 3830711.
23	955270		• Screw	Included in repair kit 3830711.
24	055000		• Washer	Included in repair kit 3830711. Included in repair kit 3830711.
25 26	955269	3	- Screw - Segment	Included in repair kit 3830711.  Included in repair kit 3830711.
27	847643	1		Included in repair kit 3830711.
28	3828598	1		moraded in repair kit eeee 7 11.
28A			· · Valve	
29	864778	1		
30	942001		· · Screw	
31	947620		Gasket     Hollow screw	
32	74033 3825126		Feed line	
34	866286	1		(849590)
J .	000200		Topan III	(8.18888)

7740910 - 25 - 3515 17561 Upd: 17 MAR 2006