

17561

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	3827451	1	Turbocharger	
2		1	Turbine housing	
3		1		
4 5			Rotor unit Bearing housing	
6		1	Shield	
7			· · Bushing	Included in repair kit 3830711.
8		4	· · Lock ring	Included in repair kit 3830711.
9		1		Included in repair kit 3830711.
10		1		Included in repair kit 3830711.
11 12		1		Included in repair kit 3830711.
13		1		
14		1		
15		1	· · Sleeve	
16		1		
17		1		
18 19		1	Nut Pressure plate	Included in repair kit 3830711.
20	845829		Screw	Included in repair kit 3830711.
21	0.10020	2		Included in repair kit 3830711.
22		1	· · O-ring	Included in repair kit 3830711.
23	955270		· Screw	Included in repair kit 3830711.
24	055000	3		Included in repair kit 3830711.
25 26	955269	3	- Screw - Segment	Included in repair kit 3830711. Included in repair kit 3830711.
27	847643	1		Included in repair kit 3830711.
28	3828598	1		molecce in repair the cocci in the
28A		1	· · Valve	
29	864778	1		
30	942001		- · Screw - · · Gasket	
31 32	947620 74033		Hollow screw	
33	3825126		• Feed line	
34	866286	1		(849590)
54	800230		Nepall Ni	(049390)

7740910 - 25 - 3515B 17561 Upd: 17 MAR 2006