

| REF      | PART NO. | QTY | DESCRIPTION      | NOTES  |
|----------|----------|-----|------------------|--|
| 1        | 471500   | 1   |                  | NOTES  |
| <u> </u> | 47 1000  |     | water pamp       |  |
| 2        |          | 1   | Housing          |  |
| 3        | 477080   | 1   |                  | Replaced by 1 ea impeller 1675808, 1 ea shaft 468249 and 1 ea seal ring 1676432. |
| 3        | 477000   | 1   | - Impelier       | Replaced by Tea impelier 107 3000, Tea shall 400249 and Tea searning 107 0432.   |
| 4        | 468249   | 1   | · · Shaft        | Included in repair kit 3830711.  |
| 4        | 400249   | 1   | · · Shart        | included in repair kit 36307 FT.   |
| 5        | 404540   | 4   | · Shaft          | Included in repair kit 3830711.  |
| 6        | 421549   |     | · Silait         |  |
|          | 471497   | 1   | · O-ring         | Included in repair kit 3830711.  |
| 7        | 3183650  | 1   |                  | (1674237). Included in repair kit 3830711.                                       |
| 8        | 471495   | 1   |                  | Included in repair kit 3830711.  |
| 9        | 421306   | 1   |                  |  |
| 10       | 1545283  | 1   | Sealing ring     |  |
| <u></u>  |          |     |                  |  |
| 12       | 958811   | 1   |                  | (469749). Included in repair kit 3830711.  |
| 13       | 471499   | 1   |                  | Included in repair kit 3830711.  |
| 14       | 471493   | 1   | Lock ring        | Included in repair kit 3830711.  |
| 15       | 471501   | 1   |                  |  |
| 16       | 11992    | 1   | Gasket           |  |
| 17       | 947107   | 1   |                  |  |
| 18       | 849971   | 1   | Plug             | Plug 849971 should be used at marine engines. Screw 947107 should dismounted.    |
| 19       | 276942   | 1   | Coolant pump kit | SEE GROUP 99   |
|          |          |     |                  |  |

