

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	471500	1		REPLACED BY 477397
	47 1000	'	Water parity	INCI ENCED DI 417001
2		1	Housing	
3	477080	1		Replaced by 1 ea impeller 1675808, 1 ea shaft 468249 and 1 ea seal ring 1676432.
	477000		Impener	replaced by 1 ca imponer 1070000, 1 ca shart 400243 and 1 ca scarning 1070402.
4	468249	1	· · Shaft	Included in repair kit 3830711.
	700273	'	- Grian	included in repair kit 3030711.
5	421549	1	Shaft	Included in repair kit 3830711.
6	471497	1		Included in repair kit 3830711.
7	1674237	1	· Cover	Included in repair kit 3630711.
8	471495	1		Included in repair kit 3830711. Included in repair kit 3830711.
9	421306	1		included in repair kit 3030711.
10	1545283	1	Sealing ring	
10	1040200	ı	- Sealing fing	
12	958811	- 1	Sealing ring	(469749). Included in repair kit 3830711.
13	471400	1	- Sealing ling	
	471499	1		Included in repair kit 3830711.
14 15	471493 471501	1	Lock ring Gear	Included in repair kit 3830711.
16	11992	1		
17	947107	1		Diverge 0.40074 about the weed of markets at 100 0.47407 to 110 0.400
18 19	849971	1		Plug 849971 should be used at marine engines. Screw 947107 should dismounted. SEE GROUP 99
19	276835	1	Overnaul kit	SEE GROUP 99