


**Change**

The latest replacement standard pistons (P/N 735-9686) for these engines use a different set of piston rings. The latest piston's oil ring groove is not as deep as the older piston.

**Replacement Parts**

The latest replacement piston will be shipped with a set of piston rings.

If piston rings only are required, refer to the drawings before ordering replacement piston ring sets from the chart.



Model	Old Piston P/N 735-9686 Ring Set	New Piston P/N 735-9686 Ring Set
5.7L	39-17464	39-801861

Parts List						
Ref	Class	Part	Description	Qty	Comment	Footnote
39		17464	OLD PISTON P/N 735-9686 RING			
39		801861	NEW PISTON P/N 735-9686 RING			