



| Parts List | | | | | | |
|------------|-------|----------|---------------------|-----|-------------|----------|
| Ref | Class | Part | Description | Qty | Comment | Footnote |
| 1 | | 98869A11 | ELECTRODE ASSEMBLY | 1 | | |
| 2 | 10 | 69067 | SCREW | 2 | | |
| 3 | 13 | 26992 | LOCKWASHER | 2 | | |
| 4 | 12 | 29245 | WASHER | 2 | | |
| 5 | 25 | 88388 | O-RING | 1 | (DESIGN I) | |
| 6 | 25 | 805294 | GROMMET | 1 | (DESIGN II) | |
| 7 | 10 | 72202 | SCREW (1-1/4 IN.) | 1 | | |
| 7 | 10 | 805565 | SCREW (3/4 IN.) | 1 | | |
| 8 | | 42600A 3 | CONTROLLER ASSEMBLY | 1 | | |
| 9 | 11 | 68219 | NUT | 4 | | |
| 10 | 84 | 88543A 3 | WIRE ASSEMBLY | 1 | | |
| 11 | | 44574 | ANODIC CAP | 2 | | |
| 12 | 10 | 62568 | SCREW | 1 | | |
| 13 | 16 | 805459 | STUD | 1 | | |
| 14 | 11 | 46438 | NUT | 2 | | |