



Parts List

| Ref | Class | Part | Description | Qty | Comment | Footnote |
|-----|-------|---------|-------------------------|-----|---------|----------|
| 1 | | 807962A | BRACKET ASSEMBLY-Shift | 1 | | |
| 2 | 16 | 98798 | STUD (.250-28 x 2.125) | 1 | | |
| 3 | 24 | 98880 | SPRING | 1 | | |
| 4 | 12 | 56720 | WASHER | 2 | | |
| 5 | 12 | 35462 | WASHER | 4 | | |
| 6 | 11 | 13438 | NUT (.250-28) | 2 | | |
| 7 | 18 | 32857 | PIN-Cotter | 1 | | |
| 8 | 23 | 98828 | SPACER | 1 | | |
| 9 | 10 | 53167 | SCREW (.312-18 x .875) | 1 | | |
| 10 | | 12381 | RETAINER-Shift Cable | 1 | | |
| 11 | 10 | 64014 | SCREW (.250-28 x .500) | 3 | | |
| 12 | 12 | 846673 | WASHER | 3 | | |
| 13 | | 816283 | ADAPTER | 1 | | |
| 14 | 11 | 63341 | TEE NUT | 1 | | |
| 15 | 18 | 21071 | PIN-Cotter | 1 | | |
| 16 | 17 | 68402 | PIN-Shoulder | 1 | | |
| 17 | 16 | 96112 | STUD-Shift Cable | 1 | | |
| 18 | 10 | 13743 | SCREW (.312-18 x 1.843) | 1 | | |
| 19 | | 13898 | LEVER-Shift | 1 | | |
| NS | 91 | 12427 | TOOL-Shift Adjust | 1 | | |