

Gasoline

			Driveshaft Housing			Gear Housing		
Model	Ref No.	Ratio	Gear Tooth Count	Gear Set Part Number	Driveshaft Housing Complete	Gear Tooth Count	Gear Set Part Number	Gear Housing Complete
Bravo One X								
Bravo One X w/DWP	1	1.36:1	29/27	43-858331A3	1589-8868H81	15/19	43-14063A1	1656-8866A63
Bravo One X w/DWP	2	1.50:1	32/27	43-858327A3	1589-8868H82	15/19	43-14063A1	1656-8866A63
Bravo One X w/DWP	3	1.65:1	30/23	43-858335A3	1589-8868H86	15/19	43-14063A1	1656-8866A63
Bravo Two X								
Bravo Two X	4	1.81:1	29/27	43-858331A3	1589-8868H81	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
Bravo Two X	5	2.00:1	32/27	43-858327A3	1589-8868H82	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
Bravo Two X	6	2.20:1	30/23	43-858335A3	1589-8868H86	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
Bravo Three X								
Bravo Three X	7	1.81:1	29/27	43-858331A3	1589-8868H81	16/27	43-822535A1	1656-8866A35
Bravo Three X	8	2.00:1	32/27	43-858327A3	1589-8868H82	16/27	43-822535A1	1656-8866A35
Bravo Three X	9	2.20:1	30/23	43-858335A3	1589-8868H86	16/27	43-822535A1	1656-8866A35

1610

Parts List									
Ref	Class	Part	Description	Qty	Comment	Footnote			
-			NS NOT SHOWN, Bravo One X	-					
1		5237100NP	STERNDRIIVE UNIT, Complete	1	(Bravo One X) (With DWP) (1.36:1				
1	1589	8868H81	DRIVESHAFT HOUSING ASSEM	1					
1	43	858331A 3	GEAR SET, (29/27)	1					
1	1656	8866A63	GEAR HOUSING ASSEMBLY, C	1					
1	43	14063A 1	GEAR SET, (15/19)	1					
2		5237200NP	STERNDRIIVE UNIT, Complete	1	(Bravo One X) (With DWP) (1.50:1				
2	1589	8868H82	DRIVESHAFT HOUSING ASSEM	1					
2	43	858327A 3	GEAR SET, (32/27)	1					
2	1656	8866A63	GEAR HOUSING ASSEMBLY, C	1					
2	43	14063A 1	GEAR SET, (15/19)	1					
3		5237300NP	STERNDRIIVE UNIT, Complete	1	(Bravo One X) (With DWP) (1.65:1				
3	1589	8868H86	DRIVESHAFT HOUSING ASSEM	1					
3	43	858335A 3	GEAR SET, (30/23)	1					
3	1656	8866A63	GEAR HOUSING ASSEMBLY, C	1					
3	43	14063A 1	GEAR SET, (15/19)	1					
-			NS NOT SHOWN, Bravo Two X	-					
4		5337400NP	STERNDRIIVE UNIT, Complete	1	(Bravo Two X) (1.81:1 Ratio)				
4	1589	8868H81	DRIVESHAFT HOUSING ASSEM	1					
4	43	858331A 3	GEAR SET, (29/27)	1					
4	1641	8294A16	GEAR HOUSING ASSEMBLY, C	1					
4	43	41656T	GEAR, (16/27)	1					
4	43	41657T	GEAR, DRIVE (16/27)	1					
5		5337600NP	STERNDRIIVE UNIT, Complete	1	(Bravo Two X) (2.00:1 Ratio)				
5	1589	8868H82	DRIVESHAFT HOUSING ASSEM	1					
5	43	858327A 3	GEAR SET, (32/27)	1					
5	1641	8294A16	GEAR HOUSING ASSEMBLY, C	1					
5	43	41656T	GEAR, (16/27)	1					
5	43	41657T	GEAR, DRIVE (16/27)	1					
6		5337500NP	STERNDRIIVE UNIT, Complete	1	(Bravo Two X) (2.20:1 Ratio)				
6	1589	8868H86	DRIVESHAFT HOUSING ASSEM	1					
6	43	858335A 3	GEAR SET, (30/23)	1					
6	1641	8294A16	GEAR HOUSING ASSEMBLY, C	1					
6	43	41656T	GEAR, (16/27)	1					
6	43	41657T	GEAR, DRIVE (16/27)	1					
-			NS NOT SHOWN, Bravo Three X	-					
7		5447400NP	STERNDRIIVE UNIT, Complete	1	(Bravo Three X) (1.81:1 Ratio)				
7	1589	8868H81	DRIVESHAFT HOUSING ASSEM	1					
7	43	858331A 3	GEAR SET, (29/27)	1					
7	1656	8866A35	GEAR HOUSING ASSEMBLY, C	1					
7	43	822535A 1	GEAR SET, (16/27)	1					