



12829

| Parts List | | | | | | |
|------------|-------|-----------|-------------------------------|-----|---------|----------|
| Ref | Class | Part | Description | Qty | Comment | Footnote |
| 1 | 56 | 42600A 3 | CONTROLLER ASSEMBLY | 1 | | |
| 2 | 11 | 68219 | NUT, (#10-32) | 4 | | |
| 3 | | 807286T | BRACKET | 1 | | |
| 4 | 10 | 40001188 | SCREW, (M10 x 20) | 1 | | |
| 5 | 12 | 40022 20 | WASHER | 1 | | |
| 6 | 10 | 40001 17 | SCREW, (M5 x 20) | 2 | | |
| 7 | 12 | 809931036 | WASHER | 2 | | |
| 8 | 11 | 855385 | NUT, (M5) | 2 | | |
| 9 | 10 | 62568 | SCREW, (#10-16 x .375) | 1 | | |
| 10 | 12 | 30164 | WASHER, (.192 x .375 x .0312) | 2 | | |
| 11 | 84 | 803625 | FUSE ASSEMBLY | 1 | | |
| - | 88 | 812619 | FUSE, Yellow (20 Ampere) | 1 | | |