



10534

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1	860233	1	Cylinder block, CYLINDER BLOCK		SN2300041850-. WITH O-RING GROOVE FOR SEALING BETWEEN CYLINDER BLOCK AND FUEL INJECTION PUMP. REPL BY 861245
				02A-5420	
2	477024	3	· Expansion plug		(192211)
3	463360	4	· Bushing		
4		2	· BEARING CAP		
5	963257	8	· Screw		
6	840210	8	· Washer		
7	3875305	6	· Guide sleeve		
8		1	· OIL SUMP		
9	840588	1	· Strainer		
10	840713	1	· Cap plug		
11	946778	1	· Cap plug		
12	192154	1	· Plug		
13	941907	12	· Spring washer		
14	840312	3	· Screw		
15	840489	2	· Screw		
16	947620	2	· Gasket		
17	840582	1	· Control rod		
18	840599	1	· Link rod		LINK ROD 858681 IS INTENDED FOR 2003T, 2003TB AND 2003TB-SOLAS.SEE GROUP 2C.
19	951665	1	· Retaining ring		
20	955300	12	· Screw		L = 50 MM
21	967592	1	O-ring	IK	
22	967590	1	O-ring	IK	
23	943177	1	O-ring	IK	
24	950586	4	Pin		
25	840846	1	Tube		
28	947893	1	Drain cock		
29	950885	2	Drive screw		
30	924061	6	Stud		
34	969011	2	Gasket		
35	840959	1	Tube		SEE GROUP 2B. CYLINDER BLOCK-TURBO COMPRESSOR
36	25167	1	Hollow screw		
37	949329	2	Gasket		
38	858151	1	Nipple		SN-2300049279
39	947622	2	Gasket		SN-2300049279
40	190713	1	Hollow screw		SN-2300049279
41	840955	1	Return pipe		SN-2300049279. TURBO COMPRESSOR-CYLINDER BLOCK. REPLACED BY 1EA 860466 RETURN PIPE, 1EA FLANGE 858152, 1EA NIPPLE 860552,1EA FERRULE 956970 AND 1EA NUT 956984
42	860466	1	Return pipe		SN2300049280-. TURBO COMPRESSOR-CYLINDER BLOCK
43	956984	1	Nut		SN2300049280-

