



REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1	834610	1	Alternator		MO-41599. REPLACED BY 834965.
				030-1000	
	834965	1			MO 41600-50116. REPLACED BY 831380.
				030-1000	
	841380	1	Alternator		MO 50117-. REPLACED BY 841770.
				030-1000	
	841770	1	Alternator		
			Bulletin 49-04	49-04-EN	Alternators
1				030-1000	
1A	840088	1	Pulley		SPEC 867374, -421, -498, -499, -540, -577.. FOR ALTERNATOR 841770.
1A	829619	1	Bracket		
	829619	1	Bracket		MO-52480. SPEC 867421, -498, -499, -540.
1A	829900	1	Bracket		MD52481-. SPEC 867421, -498, -499, -540.
3	959241	1	Screw		L = 40 MM
	959241	1	Screw		MO-52480. SPEC 867421, -498, -499, -540.
3	955318	1	Screw, SCREW		L = 30 MM. SPEC 867421, -498, -499, -540. MO 52481-
4	829601	2	Spacer sleeve		ALT
	829653	2	Sleeve		ALT, L = 15 MM
4	845589	1	Spacer sleeve		L = 8 MM. SPEC 867577.
5	960141	1	Washer		ALT
6	940132	2	Screw		
6	940132	2	Screw		MO-52480. SPEC 867421, -498, -499, -540.
	940142	2	Screw		L = 30 MM, MO 52481-. SPEC 867421, -498, -499, -540.
	955294	1	Screw		L = 16 MM, MO 52481-. SPEC 867421, -498, -499, -540.
7	955701	1	Screw		L = 89 MM
	955701	1	Screw		MO-52480. SPEC 867421, -498, -499, -540.
7	955249	1	Screw, SCREW		L = 80 MM. SPEC 867421, -498, -499, -540. MO 52481-
8	943048	X	Washer		TH = 0,15 MM
	943048	X	Washer		MO-52480. SPEC 867421, -498, -499, -540.
8	845589	1	Spacer sleeve		MO 52481-. SPEC 867421, -498, -499, -540.
9	950375	1	Nut		
	950375	1	Nut		MO-52480. SPEC 867421, -498, -499, -540.
9	963107	1	Nut		MO 52481-. SPEC 867421, -498, -499, -540.
10	958306	1	V-belt		L = 900 MM
	958306	1	V-belt		MO-52480. SPEC 867421, -498, -499, -540.
	958322	1	Drive belt, DRIVE BELT		L = 1300 MM. SPEC 867421, -498, -499, -540.
					MO 52481-

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
10	958326	1	V-belt		L = 1400 MM. FOR PULLEY 840088.
10	958332	1	V-belt		L = 1550 MM. SPEC 867577.
	958332	1	V-belt		SPEC 867577.
11	833973	1	Tensioner		
	833973	1	Tensioner		MO-52480. SPEC 867421, -498, -499, -540.
	829948	1	Tensioner		MO 52481-. SPEC 867421, -498, -499, -540.
12	940132	1	Screw		L = 35 MM
	940132	1	Screw		MO-52480. SPEC 867421, -498, -499, -540.
12	955298	1	Screw		MO 52481-. SPEC 867421, -498, -499, -540.
13	191172	1	Washer		ALT
13	941874	2	Washer		MO 52481-. SPEC 867421, -498, -499, -540.
14	941907	4	Spring washer		
14	941908	3	Spring washer		MO 52481-. SPEC 867421, -498, -499, -540.
15	955782	1	Nut		
16	833425	1	Pulley		MO-51375. SPEC 867421, -498, -540.
16	829636	1	Pulley, 2 GROOVES		MD11C/HD-RB, MD11C/HD-BT, MD11C/HD-HY.. SPEC 867499, MO-51375.
	829603	1	Pulley, 2 GROOVES		MO 51376-. SPEC 867499.
17	942336	5	Spring washer		
18	959239	4	Screw		L = 30 MM. FOR PULLEY 833425.
18	959240	4	Screw		L = 35 MM
	821042	1	Sign		