



REF	PART NO.	QTY	DESCRIPTION	NOTES
1	866406	1	Turbocharger	Replaced by 3826985.
2		1	· Compressor housing	
3		1	· Turbine housing	
4		4	· Segment	
5		8	· Screw	Included in repair kit 3830711.
6		1	· Rotor unit	REPL BY 863771
7		1	· · Turbine rotor	
8		2	· · Washer	
9		1	· · Bushing	
10		1	· · Oil deflector ring	
11		1	· · Sealing ring	
12		1	· · Compressor wheel	
13		1	· · Nut	Included in repair kit 3830711.
14		4	· · Piston ring	Included in repair kit 3830711.
15		4	· · Screw	Included in repair kit 3830711.
16		4	· · Washer	Included in repair kit 3830711.
17	849687	1	· · O-ring	Included in repair kit 3830711.
18		1	· · Cover	
19		1	· · O-ring	Included in repair kit 3830711.
20		1	· · Oil deflector	Included in repair kit 3830711.
21		1	· · Thrust bearing	Included in repair kit 3830711.
22		2	· · Bushing	Included in repair kit 3830711.
23		4	· · Lock ring	Included in repair kit 3830711.
24		1	· · Bearing housing	
25		1	· · Shield	
26		4	· · Piston ring	Included in repair kit 3830711.
27		6	· Screw	Included in repair kit 3830711.
28		3	· Segment	Included in repair kit 3830711.
29	863765	1	Repair kit	
	876804	1	Gasket kit	For mounting of the turbocharger. Bring also 4 ea sealing ring 3825197