

1

25



<u>16353</u> 7744520 - 25 - 1119

QTY	DESCRIPTION	NOTES
	Turbo	
	Turbocharger, exch	Exchange unit
	Compressor housing	
	Clamp Look put	Included in repair kit 2020711
-		Included in repair kit 3830711. Included in repair kit 3830711.
_	Lock ring	
1		Included in repair kit 3830711.
1	Piston ring	Included in repair kit 3830711.
1	Oil deflector ring	Included in repair kit 3830711.
1	Oil deflector	
		Included in repair kit 3830711.
	· Spacer	
	• Bearing	Included in repair kit 3830711.
		Included in repair kit 3830711. Included in repair kit 3830711.
2	· Washer	Included in repair kit 3830711.
	Heat shield	
	· Clamp	
	· · Lock nut	Included in repair kit 3830711.
1	Thrust ring	Included in repair kit 3830711.
1	Turbine rotor	
1	Turbine housing	
1	Repair kit	
	1     1	1   Turbo     1   Turbocharger, exch     1   Compressor housing     1   Clamp     1   Lock nut     1   Lock nut     1   Lock nut     1   Compressor wheel     1   Lock ring     1   Cover     1   Oring     1   Oring     1   Oring     1   Oil deflector ring     1   Oil deflector     2   Thrust washer     1   Spacer     1   Bearing     2   Washer     1   Bearing     2   Washer     1   Bearing     2   Washer     1   Bearing housing     1   Heat shield     1   Clamp     1   Lock nut     1   Thrust ring     1   Turbine rotor     1   Turbine housing