

REF	PART NO.	QTY	DESCRIPTION		NOTES
1	477770	1			REPLACED BY 8192050
	8192050	1			1121 21023 21 0102000
2	0102000		Housing		
3	1675808	1	• Impeller		Included in repair kit 3830711.
4	468249	1	• Shaft		Included in repair kit 3830711.
5	421549	1	• Shaft	+	Included in repair kit 3830711.
6	471497	1	· O-ring		Included in repair kit 3830711.
7	1674237	1	· Cover		Included in repair kit 3830711.
8	471495	1	Lock spring		Included in repair kit 3830711.
9	1676432	1	Sealing ring	+	Included in repair kit 3830711.
		1	Sealing ring Sealing ring		Included in repair kit 3830711.
10 11	958811 471499	1	Poll booring		Included in repair kit 3630711.
		1	• Ball bearing		Included in repair kit 3830711
12	471493	1	· Lock ring		Included in repair kit 3830711.
13	471501		• Gear		
14	11992		• Gasket		
15	947107	1	• Flange screw		
16	276835	1	Overhaul kit		SEE GROUP 99

7746660 - 26 - 1215 15401 Upd: 21 NOV 2005