

Mercruiser

Mercruiser 47-86462A-1 obsolete

Hello Sir:

I am sorry to tell you that 47-86462A-1 is no longer available from Mercruiser.

Mercruiser recommends that you replace the whole pump with a 466-9410A-1. This is available from Mercruiser, but it is expensive (see attached quote).

I did find a person who has one of the earlier impellers 14-86462 in stock. They want \$150 for it.

Let me know what you would like to do.

Thank you.

J.D.

Unique solution ID: #1034

Author:

Last update: 2015-03-12 20:09