

# Volvo Penta

## Volvo 873531 RPL 22314183 Question

Hello:

Volvo Penta is still having some issues on these, but they have contacted with a new vendor for this part. This means there is a new part number for the 873531 which is 22314183. It should be the exact same part, but from a different vendor and a new part number. However, the price has increased to \$231.54 each. This new part number is so new that it hasn't been officially entered into the parts systems as of yet.

I talked with Volvo Penta today and they said the new part number should be in their hands by February 6th (500 pieces) and then a next batch of 500 on March 6th.

Do you want to order a pair of these?

J. D. Neeson

Unique solution ID: #1084

Author:

Last update: 2015-03-03 19:35