


**Change**  
 The latest replacement standard pistons (PIN 735-9686) for these engines use a different set of piston rings. The latest piston's oil ring groove is not as deep as the older piston.

**Replacement Parts**  
 The latest replacement piston will be shipped with a set of piston rings.  
 If piston rings only are required, refer to the drawings before ordering replacement piston ring sets from the chart.



Model	Old Piston PIN 735-9686 Ring Set	New Piston PIN 735-9686 Ring Set
4.3L/LX	39-17464	39-801861

Parts List						
Ref	Class	Part	Description	Qty	Comment	Footnote
1	735	808674	PISTON AND PISTON PIN (STAN	6		
2	39	17464	PISTON RING (STANDARD)	6		
3/4	23	818465	MAIN BEARING SET (STANDARD)	1		
3/4	23	818466	MAIN BEARING SET (.001 U.S.)	AR		
3/4	23	818467	MAIN BEARING SET (.010 U.S.)	AR		
3/4	23	818468	MAIN BEARING SET (.020 U.S.)	AR		
5	17	35312	DOWEL PIN	2		
6	222	824320	FLYWHEEL	1		
7	10	49845	SCREW	6		
9		18643A	COUPLING ASSEMBLY	1		
10		18644	RUBBER BUMPER	3		
11	10	14883	SCREW	3		
12	12	13510	WASHER	3		
12A	22	74036	GREASE FITTING	1		
13	614	811839	CONNECTING ROD	6		
14	10	11969	BOLT	12		
15	11	37493	NUT	12		
16	23	11992	BEARING UNIT (STANDARD - PA	6		
16	23	11993	BEARING UNIT (.001 U.S. - PAIR)	AR		
16	23	811858	BEARING UNIT (.010 U.S. - PAIR)	AR		
16	23	811859	BEARING UNIT (.020 U.S. - PAIR)	AR		
17	429	9517A	CRANKSHAFT	1		
18	28	818485	KEY	1		