

**Bravo Standard**

Model	Ref. No.	Ratio	Driveshaft Housing			Gear Housing		
			Gear Tooth Count	Gear Set Part Number	Driveshaft Housing Complete	Gear Tooth Count	Gear Set Part Number	Gear Housing Complete
<b>Bravo One</b>								
Bravo One w/LWP	1	1.36:1	29/27	43-859779A3	1589-8868H87	15/19	43-14063A1	1656-8866A55
Bravo One w/LWP	2	1.50:1	32/27	43-859776A3	1589-8868H89	15/19	43-14063A1	1656-8866A55
Bravo One w/LWP	3	1.65:1	30/23	43-859782A3	1589-8868H88	15/19	43-14063A1	1656-8866A55
Bravo One w/DWP	4	1.36:1	29/27	43-859779A3	1589-8868H87	15/19	43-14063A1	1656-8866A63
Bravo One w/DWP	5	1.50:1	32/27	43-859776A3	1589-8868H89	15/19	43-14063A1	1656-8866A63
Bravo One w/DWP	6	1.65:1	30/23	43-859782A3	1589-8868H88	15/19	43-14063A1	1656-8866A63
<b>Bravo Two</b>								
Bravo Two	7	1.50:1	29/27	43-859779A3	1589-8868H87	18/25	(P)43-827304T (D)43-827303	1641-8294A19
Bravo Two	8	1.65:1	32/27	43-859776A3	1589-8868H89	18/25	(P)43-827304T (D)43-827303	1641-8294A19
Bravo Two	9	1.81:1	29/27	43-859779A3	1589-8868H87	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
Bravo Two	10	2.00:1	32/27	43-859776A3	1589-8868H89	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
Bravo Two	11	2.20:1	30/23	43-859782A3	1589-8868H88	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
<b>Bravo Three</b>								
Bravo Three	12	1.36:1	29/27	43-859779A3	1589-8868H87	15/19	43-805448A1	1656-8866A37
Bravo Three	13	1.50:1	32/27	43-859776A3	1589-8868H89	15/19	43-805448A1	1656-8866A37
Bravo Three	14	1.65:1	32/27	43-859776A3	1589-8868H89	18/25	43-824517A1	1656-8866A35
Bravo Three	15	1.81:1	29/27	43-859779A3	1589-8868H87	16/27	43-822535A1	1656-8866A35
Bravo Three	16	2.00:1	32/27	43-859776A3	1589-8868H89	16/27	43-822535A1	1656-8866A35
Bravo Three	17	2.20:1	30/23	43-859782A3	1589-8868H88	16/27	43-822535A1	1656-8866A35
Bravo Three	18	2.43:1	30/23	43-859782A3	1589-8868H88	13/24	43-828336A1	1656-8866A51

1608

Parts List								
Ref	Class	Part	Description	Qty	Comment	Footnote		
-	F596		BRAVO ONE	-				
1	5	5C31100LP	STERNDRIVE UNIT COMPLETE	1	(Bravo One) (WITH LWP) (1.36:1			
1	1589	8868H87	DRIVESHAFT HOUSING ASSEM	1				
1	43	859779A 3	GEAR SET, (29/27)	1				
1	1656	8866A55	GEAR HOUSING ASSEMBLY (C	1				
1	43	14063A 1	GEAR SET, (15/19)	1				
2	5	5C31200LP	STERNDRIVE UNIT COMPLETE	1	(Bravo One) (WITH LWP) (1.50:1			
2	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1				
2	43	859776A 3	GEAR SET, (32/27)	1				
2	1656	8866A55	GEAR HOUSING ASSEMBLY (C	1				
2	43	14063A 1	GEAR SET, (15/19)	1				
3	5	5C31300LP	STERNDRIVE UNIT (Complete)	1	(Bravo One) (WITH LWP) (1.65:1			
3	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1				
3	43	859782A 3	GEAR SET, (30/23)	1				
3	1656	8866A55	GEAR HOUSING ASSEMBLY (C	1				
3	43	14063A 1	GEAR SET, (15/19)	1				
4	5	5231100NP	STERNDRIVE UNIT (Complete)	1	(Bravo One) (WITH DWP) (1.36:1			
4	1589	8868H87	DRIVESHAFT HOUSING ASSEM	1				
4	43	859779A 3	GEAR SET, (29/27)	1				
4	1656	8866A63	GEAR HOUSING ASSEMBLY (C	1				
4	43	14063A 1	GEAR SET, (15/19)	1				
5	5	5231200NP	STERNDRIVE UNIT (Complete)	1	(Bravo One) (WITH DWP) (1.50:1			
5	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1				
5	43	859776A 3	GEAR SET, (32/27)	1				
5	1656	8866A63	GEAR HOUSING ASSEMBLY (C	1				
5	43	14063A 1	GEAR SET, (15/19)	1				
6	5	5231300NP	STERNDRIVE UNIT (Complete)	1	(Bravo One) (WITH DWP) (1.65:1			
6	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1				
6	43	859782A 3	GEAR SET, (30/23)	1				
6	1656	8866A63	GEAR HOUSING ASSEMBLY (C	1				
6	43	14063A 1	GEAR SET, (15/19)	1				
-	F596		BRAVO ONE	-				
7	5	5331200LP	STERNDRIVE UNIT (Complete)	1	(Bravo Two) (1.50:1 Ratio)			
7	1589	8868H87	DRIVESHAFT HOUSING ASSEM	1				
7	43	859779A 3	GEAR SET, (29/27)	1				
7	1641	8294A19	GEAR HOUSING ASSEMBLY (C	1				
7	43	827304T	GEAR, (18/25)	1				
7	43	827303	GEAR, DRIVE	1				
8	5	5331300LP	STERNDRIVE UNIT (Complete)	1	(Bravo Two) (1.65:1 Ratio)			
8	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1				
8	43	859776A 3	GEAR SET, (32/27)	1				