

Bravo Standard

Model	Ref. No.	Ratio	Driveshaft Housing			Gear Housing		
			Gear Tooth Count	Gear Set Part Number	Driveshaft Housing Complete	Gear Tooth Count	Gear Set Part Number	Gear Housing Complete
Bravo One								
Bravo One w/LWP	1	1.36:1	29/27	43-859779A3	1589-8868H87	15/19	43-14063A1	1656-8866A55
Bravo One w/LWP	2	1.50:1	32/27	43-859776A3	1589-8868H89	15/19	43-14063A1	1656-8866A55
Bravo One w/LWP	3	1.65:1	30/23	43-859782A3	1589-8868H88	15/19	43-14063A1	1656-8866A55
Bravo One w/DWP	4	1.36:1	29/27	43-859779A3	1589-8868H87	15/19	43-14063A1	1656-8866A63
Bravo One w/DWP	5	1.50:1	32/27	43-859776A3	1589-8868H89	15/19	43-14063A1	1656-8866A63
Bravo One w/DWP	6	1.65:1	30/23	43-859782A3	1589-8868H88	15/19	43-14063A1	1656-8866A63
Bravo Two								
Bravo Two	7	1.50:1	29/27	43-859779A3	1589-8868H87	18/25	(P)43-827304T (D)43-827303	1641-8294A19
Bravo Two	8	1.65:1	32/27	43-859776A3	1589-8868H89	18/25	(P)43-827304T (D)43-827303	1641-8294A19
Bravo Two	9	1.81:1	29/27	43-859779A3	1589-8868H87	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
Bravo Two	10	2.00:1	32/27	43-859776A3	1589-8868H89	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
Bravo Two	11	2.20:1	30/23	43-859782A3	1589-8868H88	16/27	(P)43-41656T (D)43-41657T	1641-8294A16
Bravo Three								
Bravo Three	12	1.36:1	29/27	43-859779A3	1589-8868H87	15/19	43-805448A1	1656-8866A37
Bravo Three	13	1.50:1	32/27	43-859776A3	1589-8868H89	15/19	43-805448A1	1656-8866A37
Bravo Three	14	1.65:1	32/27	43-859776A3	1589-8868H89	18/25	43-824517A1	1656-8866A35
Bravo Three	15	1.81:1	29/27	43-859779A3	1589-8868H87	16/27	43-822535A1	1656-8866A35
Bravo Three	16	2.00:1	32/27	43-859776A3	1589-8868H89	16/27	43-822535A1	1656-8866A35
Bravo Three	17	2.20:1	30/23	43-859782A3	1589-8868H88	16/27	43-822535A1	1656-8866A35
Bravo Three	18	2.43:1	30/23	43-859782A3	1589-8868H88	13/24	43-828336A1	1656-8866A51

1608

Parts List

Ref	Class	Part	Description	Qty	Comment	Footnote
-	F596		BRAVO ONE	-		
1	5	5C31100LP	STERNDRIVE UNIT COMPLETE	1	(Bravo One) (WITH LWP) (1.36:1)	
1	1589	8868H87	DRIVESHAFT HOUSING ASSEM	1		
1	43	859779A 3	GEAR SET, (29/27)	1		
1	1656	8866A55	GEAR HOUSING ASSEMBLY (C	1		
1	43	14063A 1	GEAR SET, (15/19)	1		
2	5	5C31200LP	STERNDRIVE UNIT COMPLETE	1	(Bravo One) (WITH LWP) (1.50:1)	
2	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1		
2	43	859776A 3	GEAR SET, (32/27)	1		
2	1656	8866A55	GEAR HOUSING ASSEMBLY (C	1		
2	43	14063A 1	GEAR SET, (15/19)	1		
3	5	5C31300LP	STERNDRIVE UNIT (Complete)	1	(Bravo One) (WITH LWP) (1.65:1)	
3	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1		
3	43	859782A 3	GEAR SET, (30/23)	1		
3	1656	8866A55	GEAR HOUSING ASSEMBLY (C	1		
3	43	14063A 1	GEAR SET, (15/19)	1		
4	5	5231100NP	STERNDRIVE UNIT (Complete)	1	(Bravo One) (WITH DWP) (1.36:1)	
4	1589	8868H87	DRIVESHAFT HOUSING ASSEM	1		
4	43	859779A 3	GEAR SET, (29/27)	1		
4	1656	8866A63	GEAR HOUSING ASSEMBLY (C	1		
4	43	14063A 1	GEAR SET, (15/19)	1		
5	5	5231200NP	STERNDRIVE UNIT (Complete)	1	(Bravo One) (WITH DWP) (1.50:1)	
5	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1		
5	43	859776A 3	GEAR SET, (32/27)	1		
5	1656	8866A63	GEAR HOUSING ASSEMBLY (C	1		
5	43	14063A 1	GEAR SET, (15/19)	1		
6	5	5231300NP	STERNDRIVE UNIT (Complete)	1	(Bravo One) (WITH DWP) (1.65:1)	
6	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1		
6	43	859782A 3	GEAR SET, (30/23)	1		
6	1656	8866A63	GEAR HOUSING ASSEMBLY (C	1		
6	43	14063A 1	GEAR SET, (15/19)	1		
-	F596		BRAVO ONE	-		
7	5	5331200LP	STERNDRIVE UNIT (Complete)	1	(Bravo Two) (1.50:1 Ratio)	
7	1589	8868H87	DRIVESHAFT HOUSING ASSEM	1		
7	43	859779A 3	GEAR SET, (29/27)	1		
7	1641	8294A19	GEAR HOUSING ASSEMBLY (C	1		
7	43	827304T	GEAR, (18/25)	1		
7	43	827303	GEAR, DRIVE	1		
8	5	5331300LP	STERNDRIVE UNIT (Complete)	1	(Bravo Two) (1.65:1 Ratio)	
8	1589	8868H89	DRIVESHAFT HOUSING ASSEM	1		
8	43	859776A 3	GEAR SET, (32/27)	1		