



| | | | | Parts List | | |
|-----|-------|----------|-----------------------------|------------|---------|----------|
| Ref | Class | Part | Description | Qty | Comment | Footnote |
| - | 50 | 65784A 1 | STARTER MOTOR ASSEMBLY,CI | 1 | | |
| - | 50 | 65785A 1 | STARTER MOTOR ASSEMBLY,CI | .1 | | |
| 1 | | 68610 | HOUSING, DRIVE END | 1,1 | | |
| 2 | 23 | 33278 | BUSHING, DRIVE END HOUS | 1,1 | | |
| 3 | | 33292 | COLLAR, THRUST - DRIVE ENC | 1,1 | | |
| 4 | 53 | 33290 | RING, RETAINING - PINION ST | 1,1 | | |
| 5 | | 33291 | COLLAR, PINION STOP - DRIVE | 1,1 | | |
| 6 | | 68608 | DRIVE ASSEMBLY, CLUTCH - A | .1 | | |
| 6 | | 68609 | DRIVE ASSEMBLY, CLUTCH - A | .1 | | |
| 7 | 23 | 33369 | BUSHING, GEAR END - CLUT | 1,1 | | |
| 8 | 24 | 33368 | SPRING, CLUTCH DRIVE | 1,1 | | |
| 9 | | N. S. S. | COLLAR, CLUTCH DRIVE (DE | 1,1 | | |
| 10 | | 33367 | LOCKWIRE, COLLAR AND SP | 1,1 | | |
| 11 | | 68620 | PLATE, BEARING | 1,1 | | |
| 12 | 23 | 68616 | BUSHING, BEARING PLATE | 1,1 | | |
| 13 | 12 | 68614 | WASHER, BEARING PLATE | 1,1 | | |
| 14 | 10 | 68612 | SCREW, BEARING PLATE ATT | 2,2 | | |
| 15 | 13 | 68611 | LOCKWASHER, BEARING PLAT | 2,2 | | |
| 16 | | 68606 | ARMATURE | 1, | | |
| 16 | | 68607 | ARMATURE | .1 | | |
| 17 | | 48263 | SHOE, POLE - FIELD COIL | 4,4 | | |
| 18 | 10 | 45533 | SCREW, POLE SHOE TO FIELD | 4,4 | | |
| 19 | 25 | 68618 | GROMMET, FIELD COIL - FIELD | OPT.,0 | | |
| 19 | 25 | 68619 | GROMMET, FIELD COIL - FIELD | OPT.,0 | | |
| 20 | | 68598 | FIELD COIL ASSEMBLY | 1, | | |
| 20 | | 68599 | FIELD COIL ASSEMBLY | .1 | | |
| 21 | | 68605 | COIL, SHUNT - FIELD COIL | 1,1 | | |
| 22 | 12 | 68613 | WASHER, LEATHER - COMMUT | 1,1 | | |
| 23 | | 33295 | FRAME, COMMUTATOR END - I | 1,1 | | |
| 24 | 10 | 33286 | BOLT, THRU - COMMUTATOR E | 2,2 | | |
| 25 | | 33284 | HOLDER, INSULATED - FIELD F | 2,2 | | |
| 26 | | 33283 | HOLDER, FIELD FRAME BRUSH | 2,2 | | |
| 27 | | 33270 | BRUSH, FIELD FRAME | 4,4 | | |
| 28 | 10 | 46888 | SCREW, BRUSH LEAD TO FIEL | 2,2 | | |
| 28 | 10 | 60685 | SCREW, BRUSH LEAD TO FIEL | 2,2 | | |
| 29 | | 33294 | SUPPORT PACKAGE, GROUND | 2,2 | | |
| 30 | 17 | 45535 | PIN, GROUND AND INSULATI | 1,1 | | |
| 31 | | 60686 | LEAD, FIELD FRAME BRUSH | 2,2 | | |
| 32 | 10 | 33250 | SCREW, SUPPORT TO FIELD | 4,4 | | |
| 33 | 13 | 26396 | LOCKWASHER, SUPPORT SC | 4,4 | | |