



Quicksilver Lubrication/Sealant
 Application Points

-  Loctite 271 (Obtain Locally)
-  Loctite Primer "T" (92-59327-1)

Parts List						
Ref	Class	Part	Description	Qty	Comment	Footnote
11			GASKET-COVER PLATE	3		5,6
12			SPRING-IDLE NEEDLE	3		5
13			IDLE NEEDLE	2		5
14	1395	808746 1	THROTTLE LEVER (TOP/BOTT	2		
15	1395	823632	THROTTLE SHAFT (TOP/BOTT	2		
16			SPRING-THROTTLE RETURN	3		5
17	1395	808738	GASKET-NOZZLE WELL	3		5
18			GASKET-FUEL BOWL	3		5,6
19	1395	9595 1	INLET NEEDLE VALVE	3		5,1
20	1395	9594	FLOAT	3		
21	1395	811695	FUEL BOWL (UPPER)	1	(WME-60)	
21	1395	811693	FUEL BOWL (CENTER/LOWER	2	(WME-60)	
21	1395	811693	FUEL BOWL	3	(WME-59/61/62/75/76/77/78)	
22	1395	808612	SCREW-FUEL BOWL	12		
23	1395	811694	PLUG KIT	3		
24	1395	802731	SEAL (CONSISTS OF 4 SEALS	1		5
25	1395	6359	MAIN FUEL JET (.052)(TOP)	2	(WME-59)	
25	1399	5225	MAIN FUEL JET (.054)(CENTER.	1	(WME-59)	
25	1399	5225	MAIN FUEL JET (.054)	3	(WME-60/61/76/77)	
25	1399	4217	MAIN FUEL JET (.062)(TOP)	2	(WME-62)	
25	1399	4216	MAIN FUEL JET (.064)(CENTER.	1	(WME-62)	
25	1395	7394	MAIN FUEL JET (.044)	2	(BELGIUM)	
25	1395	6359	MAIN FUEL JET (.052)(TOP)	1	(WME-75)	
25	1399	5225	MAIN FUEL JET (.054)(CENTER.	2	(WME-75)	
25	1399	4217	MAIN FUEL JET (.062)(TOP)	1	(WME-78)	
25	1399	4216	MAIN FUEL JET (.064)(CENTER.	2	(WME-78)	
-	1395	811223 1	CARB GASKET KIT	1		5
-	1395	823635 4	CARB REPAIR KIT	1		1