

| REF | PART NO. | QTY | DESCRIPTION          | L  | NOTES   |
|-----|----------|-----|----------------------|----|---|
|     |          |     |                      |    |   |
| 1   | 3826153  | 1   | Circulation pump     |    |   |
| 2   | 014460   | 1   | - Housing            | _  | Included in everboul kit                            |
| 3   | 914462   | 1   | Lock ring     Shaft  |    | Included in overhaul kit. Included in overhaul kit. |
| 5   | 181538   | 1   | Ball bearing         |    | Included in overhaul kit.                           |
| 6   | 866189   | 1   | Ball bearing     Hub | SO | meradea in everriadi kit.                           |
| 7   | 914533   | 1   | · Snap ring          |    | Included in overhaul kit.                           |
| 8   | 1660609  | 1   | Ball bearing         |    | Included in overhaul kit.                           |
|     |          |     |                      |    |   |
| 40  | 4070400  | 4   |                      |    |   |
| 10  | 1676432  | 1   | Sealing ring         |    | Included in overhaul kit.                           |
| 12  |          | 1   | - Impeller           |    | Included in overhaul kit.                           |
| 13  | 479977   | 1   | • Plug               |    | included in overnadi kit.                           |
| 14  | 968145   | 1   | · Plug               |    |   |
| 15  | 876840   | 1   | Overhaul kit         |    | SEE GROUP 99  |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |
|     |          |     |                      |    |   |

7740910 - 26 - 578B 15147 Upd: 17 MAR 2006