

REF	PART NO.	QTY	DESCRIPTION	NOTES
	400750		10/	
1 2	420759	1	Water pump Housing	
3	1674013	1		Replaced by 1 ea impeller 1675808, 1 ea shaft 468249 and 1 ea seal ring 1676432
3	1074013	'	· Impelier	Included in repair kit 3830711.
				included in repair kit 3030711.
4	468249	1	Shaft	Included in repair kit 3830711.
5	421549	1		Included in repair kit 3830711.
6	471497	1		Included in repair kit 3830711.
7	1674237	1	 Cover 	Included in repair kit 3830711.
8	471495	1	 Lock spring 	Included in repair kit 3830711.
11	1676432	1		Included in repair kit 3830711.
12	958811	1		(469479). Included in repair kit 3830711.
13 14	471499 471493	1		Included in repair kit 3830711. Included in repair kit 3830711.
15	471493	1	Lock ring Gear	included in repair kit 3030711.
16	11992		- Gear	
17	947107	1		
18	849971	1		Plug 849971 should be used at marine engines. Screw 947107 should dismounted.
19	276835	1		SEE GROUP 99
			1	