
TWD1031VE



Upd: 2006-11-24



<u>15914</u> 7738460 - 25 - 2107

TWD1031VE

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	865812	1	Turbocharger	
	3802077	1		
2		1	Turbine housing	
3		1	Rotor unit	
4		1	• • Turbine rotor	
5		1	Compressor wheel	
6		1	· · Lock nut	Included in repair kit 273873.
7		1		
8		4	· · Screw	
9		4	· · Washer	
10		1	· · Gasket	
11		2	Piston ring	Included in repair kit 273873.
12		1	· · Spacer	Included in repair kit 273873.
13		1	· · Collar	
14		1	Thrust bearing	Included in repair kit 273873.
15		3	· · Screw	Included in repair kit 273873.
16		2	Bearing	Included in repair kit 273873.
17		3		Included in repair kit 273873.
18		1	Bearing housing Heat shield	
19		1		Included in tersit Lit 070070
20 21		1 8	· · · Piston ring · Screw	Included in repair kit 273873.
21				Included in repair kit 273873.
22		4	Clamp Compressor housing	Included in repair kit 273873.
		1	Compressor housing O-ring	Included in repair kit 273873.
24 25		1	Clamp	
25		1	Gasket	+
20		1	• Gasket	+
27		1	· Gasket	
20		1	Lock nut	
30	273873	1		1
773846	60 - 25 - 210	7	15914	Upd: 2006-11-24

TAD1030V, TD100G-87, TD1030VE, TWD1031VE

