




Parts Catalog - Option Detail

Electronic Parts Catalog - Option Detail				
Option	Group	Graphic	Film Card	Date
OB6712-01	07.04	fr401ga	K38	13-DEC-93
Engines	GTA38, K38, KTA38GC CM558, QSK38 CM2150 K106, QSK38 CM2150 MCRS, QSK38 CM850 MCRS			

©Cummins Inc



1

fr401ga

[SMALL](#) | [MEDIUM](#) | [LARGE](#)

Cart	Ref No	Part Number	Part Description	Required	Remarks
View My Cart					
		OB6712-01	Air Cylinder Lubrication Hose		Plugs for left bank and right...(More)
					bank breathers. For use when
					air actuated throttle lever
					is not specified.
<input type="checkbox"/>	1	3628604	Pipe Plug	2	1/8 - 27 X 0.3 in.