

18019

REF 1	PART NO. 3826985	QTY 1	DESCRIPTION Turbo		NOTES
1	3826985	1			Exchange unit
2	3602060	1			Exchange unit
3			Turbine housing		
4		1	Segment		
5			• Screw		Included in repair kit 3830711
6		1	Rotor unit		ilicidded iii fepail kit 30307 FT
7		1	Turbine rotor		
8			• • Washer		
9			Bushing		
10		1	Oil deflector ring		
11		1	Sealing ring		
12		1			
13		1			Left hand threads.
14			· · Piston ring		Included in repair kit 3830711
15		4	· · Screw		Included in repair kit 3830711
16			· · Washer		Included in repair kit 3830711
17	849687		· · O-ring		Included in repair kit 3830711
18	049007	1	· · Cover		ilicidded iii fepail kit 36307 i i
19		1		-	Included in repair kit 3830711
20			Oring Oli deflector	\vdash	Included in repair kit 3830711
21		1	Oil deflector Thrust bearing	1	Included in repair kit 3830711
22		2	Bushing	-	Included in repair kit 3830711
					Included in repair kit 3830711
23		4	· · Lock ring		Included in repair kit 3830711
24		1	Bearing housing Shield	-	
25				-	In alcohold in your size life 0000744
26		4	· · Piston ring		Included in repair kit 3830711
27		ď	• Screw	-	Included in repair kit 3830711
28 29	863765	1	Segment Repair kit		Included in repair kit 3830711

