

REF	PART NO.	QTY	DESCRIPTION		NOTES
1	3827451	1	Turbocharger	SO	
2		1			
3		1			
5		1			
6		1	Shield		
7		2			Included in repair kit 3830711.
8		4	· · Lock ring		Included in repair kit 3830711.
9		1	· · Piston ring		Included in repair kit 3830711.
10		1			Included in repair kit 3830711.
11		1			Included in repair kit 3830711.
12		1	· · Turbine rotor		
13		1			
14 15		1			
16		1			
17		1			
18		1			Included in repair kit 3830711.
19		1	· · Pressure plate		
20	845829	4			Included in repair kit 3830711.
21			· · Piston ring		Included in repair kit 3830711.
22		1	· · O-ring		Included in repair kit 3830711.
23	955270	6	· Screw		Included in repair kit 3830711.
24	055000	3			Included in repair kit 3830711.
25	955269	6	· Screw		Included in repair kit 3830711.
26		2	· Segment		Included in repair kit 3830711.
27	847643	1			Included in repair kit 3830711.
28	3828598	1			iliciadea ili repaii kit 30307 11.
	0020000		varo, m		
28A		1	· · Valve		
29	864778	1			
30	942001		· · Screw		
31	947620	4			
32	74033		· · Hollow screw		
33	3825126	1			(2.425.22)
34	866286	1	Repair kit		(849590)

7740790 - 25 - 3515B 17561 Upd: 30 MAR 2006