



5779

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	842427	1	Turbo	
	3802009	1	Turbocharger, exch	Exchange unit
2		1	· TURBINE HOUSING	
3	843420	1	· Rotor unit	
4		1	· · BEARING HOUSING	
5	467554	1	· · Turbine rotor	
6		2	· · PISTON RING	IK
7	467026	2	· · Thrust ring	
8	422660	1	· · Spacer sleeve	
9		2	· · BEARING	IK
10	467556	1	· · Ring retainer	
11	417727	4	· · Lock ring	IK
12		1	· · SLEEVE	IK
13		1	· · THRUST BEARING	IK
14	422662	1	· · Splash plate	IK
15	467557	1	· · Cover	
16		1	· · O-RING	IK
17	420467	1	· · Lock ring	
18	467558	1	· · Compressor wheel	
19	1518784	1	· · Nut	(422669)
20	417378	1	· · Gasket	IK
21	417381	1	· · Gasket	IK
22		1	· · TURBINE BACKPLATE	
23	422360	1	· · Lock ring	IK
24		1	· HOUSING	
25	940100	8	· Screw	
26	843422	8	· Washer	
27	417382	1	· Gasket	IK
28	961896	8	· Plug	
29	957188	8	· Gasket	
30	955524	10	· Screw	
31	941907	10	· Spring washer	
32	955984	10	· Sealing ring	
33	843421	4	· Washer	
	843424	1	Repair kit	