



5779

| REF | PART NO. | QTY | DESCRIPTION | NOTES |
|-----|----------|-----|-----------------------|----------|
| 1 | 844452 | 1 | Turbo | CLASS |
| 2 | | 1 | · TURBINE HOUSING | |
| 3 | 843420 | 1 | · Rotor unit | |
| 4 | | 1 | · · BEARING HOUSING | |
| 5 | 467554 | 1 | · · Turbine rotor | |
| 6 | | 2 | · · PISTON RING | IK |
| 7 | 467026 | 2 | · · Thrust ring | |
| 8 | 422660 | 1 | · · Spacer sleeve | |
| 9 | | 2 | · · BEARING | IK |
| 10 | 467556 | 1 | · · Ring retainer | |
| 11 | 417727 | 4 | · · Lock ring | IK |
| 12 | | 1 | · · SLEEVE | IK |
| 13 | | 1 | · · THRUST BEARING | IK |
| 14 | 422662 | 1 | · · Splash plate | IK |
| 15 | 467557 | 1 | · · Cover | |
| 16 | | 1 | · · O-RING | IK |
| 17 | 420467 | 1 | · · Lock ring | |
| 18 | 467558 | 1 | · · Compressor wheel | |
| 19 | 1518784 | 1 | · · Nut | (422669) |
| 20 | 417378 | 1 | · · Gasket | IK |
| 21 | 417381 | 1 | · · Gasket | IK |
| 22 | | 1 | · · TURBINE BACKPLATE | |
| 23 | 422360 | 1 | · · Lock ring | IK |
| 24 | | 1 | · HOUSING | |
| 25 | 940100 | 8 | · Screw | |
| 26 | 843422 | 8 | · Washer | |
| 27 | 417382 | 1 | · Gasket | IK |
| 28 | 961896 | 8 | · Plug | |
| 29 | 957188 | 8 | · Gasket | |
| 30 | 955524 | 10 | · Screw | |
| 31 | 941907 | 10 | · Spring washer | |
| 32 | 955984 | 10 | · Sealing ring | |
| 33 | 843421 | 4 | · Washer | |
| | 843424 | 1 | Repair kit | |