

PART NO.	QTY	DESCRIPTION	NOTES
			Also avaible as an exchange part.
010270			7 100 dvalblo do ali oxonango part.
	1	· Shield	
	2	Bushing	Included in repair kit 3830711.
			Included in repair kit 3830711.
			Included in repair kit 3830711.
			Included in repair kit 3830711.
			Included in repair kit 3830711.
			Included in repair kit 3830711.
	1	Rotor kit	Replaced by 1 ea rotor 3827354, 1 ea compressor wheel 3827363 and 1 ea overhaul kit 3827366.
	1		
	1	· · Compressor wheel	
	1	· · Thrust ring	
	1	· · Sleeve	
	1	· · Bushing	
	1	· · Seal	
	1	· Nut	Included in repair kit 3830711.
845829			Included in repair kit 3830711.
847643			Included in repair kit 3830711.
955270		Screw	(858661). Included in repair kit 3830711.
			Included in repair kit 3830711.
			Included in repair kit 3830711.
955269			Included in repair kit 3830711.
	3		Included in repair kit 3830711.
			SEE GROUP 99
	848276 845829 847643	848276 1 1 1 1 1 1 2 1 2 4 1 1 1 1 1 1 1 1 1 1	848276 1 Turbo 1 Turbine housing 1 Compressor housing 1 Bearing housing 1 Shield 2 Bushing 1 Piston ring 2 Piston ring 4 Lock ring 1 Thrust bearing 1 Oil deflector 1 Rotor kit 1 Compressor wheel 1 Thrust ring 1 Sleeve 1 Nut 1 Pressure plate 845829 Screw 847643 O-ring 955270 Screw 1 Oring 4 Washer 955269 Screw 3 Segment 849590 Repair kit

