


KAD42P-A, KAMD42P-A



KAD42P-A, KAMD42P-A

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1	(875000)	1	Thermo monitor		For engines with reverse gear., Obsolete part 80°C
2	828761	1	• Thermo monitor		
3	828750	1	• Nut		
4	828776	2	• Washer		
5	828817	1	• Sensor		
6	973122	2	• Cable terminal	1963	
	949597	2	• Housing	1963	