


TAMD122P-A



16779

TAMD122P-A

| REF | PART NO. | QTY | DESCRIPTION | SEE SEC. | NOTES |
|-----|----------|-----|---------------------------------------|-------------|-----------------------------------|
| 2 | 863169 | 1 | Pressure monitor, oil pressure-engine | | SN1101051157/XXXXXX- |
| 5 | 822858 | 1 | Thermo monitor, coolant water | | |
| 6 | 827150 | 1 | Sensor, coolant water | | |
| | 837044 | 1 | Temperature sensor, coolant water | | For double instruments. |
| 6D | 947622 | 1 | Gasket | | |
| 7A | 866839 | 1 | Sensor, reverse gear | | 0-30 bar |
| 8 | 947624 | 1 | Gasket | | |
| 11 | 3013297 | 1 | Tachometer sensor | | |
| 12 | 863604 | 1 | Gasket | | |
| 13 | 866835 | 1 | Sensor, oil-engine | | |
| | | | Bulletin P-38-6-1 | P-38-6-1-EN | Vibration Damping Kit |
| 13 | 866836 | 1 | Sensor, oil-engine | | For double instruments., 0-10 bar |
| 14 | 965560 | 1 | Bracket | | |
| 15 | 3574797 | 2 | Vibration damper | | |
| 16 | 479979 | 1 | Plug | | |
| 17 | 180110 | 1 | Elbow nipple | | |
| 18 | 949278 | 2 | Flange lock nut | | |
| 19 | 1507501 | 1 | Hose assembly | | |
| 20 | (955558) | 1 | Hexagon screw | | Obsolete part |
| 21 | 940280 | 1 | Spring washer | | |
| 22 | 866704 | 1 | Bracket | | |
| 23 | 866837 | 1 | Sensor, turbo | | |
| 24 | 947624 | 1 | Gasket | | |
| 25 | 944717 | 2 | Support sleeve | | |
| 26 | 954364 | 2 | Sleeve | | |
| 27 | 954356 | 2 | Fitting nut | | |
| 28 | 954385 | 2 | Elbow nipple | | |
| 29 | 843698 | 1 | Bracket | | |
| 30 | 965175 | 1 | Flange screw | | |
| 31 | 949278 | 1 | Flange lock nut | | |
| 32 | 945460 | 1 | Tube | | 710mm |