

VOLVO PENTA



<u>17561</u> **7738900-25-3518**

Turbocharger, Components: 3827914

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	3802099	1	Turbocharger	(3827914)
2		1	Turbine housing	
3		1	Compressor housing	
4		1	Rotor unit	
5		1	Bearing housing	
6		1	Heat shield	
7		2	Bushing	Included in repair kit 3830711.
8		4	Lock ring	Included in repair kit 3830711.
9		1	Piston ring	Included in repair kit 3830711.
10			Thrust bearing	Included in repair kit 3830711.
11 12		1	Oil deflector Turbine rotor	
13		1	Compressor wheel	
14		2	• Thrust washer	
15		<u> </u>	Sleeve	
16		1	Bushing	
17		1	• • Seal	
18		1	• • Nut	Included in repair kit 3830711.
19		1	Thrust plate	
20		4	Screw	Included in repair kit 3830711.
21		2	Piston ring	Included in repair kit 3830711.
22		1	• • O-ring	Included in repair kit 3830711.
23		8	Screw	
24		4	Washer	
25	(866254)	8		Obsolete part, Included in repair kit 3830711.
26		4	Segment	
27	847643			Included in repair kit 3830711.
28	3828599		 Valve, kit 	
28A		1	• • Valve	
29	864778	1	• • Gasket	
30	942001		Hex. socket screw	
31	947620		Gasket	
32	74033	2	Hollow screw	
33 34	3827545 3829955	1	Pressure oil line Overhaul kit	
73890	00-25-3518		17561	Upd:2011-11-2

