
TWD1031VE



Upd: 2006-11-24

VOLVO PENTA

TWD1031VE

Included in repair kit 2738	1 · Rotor unit	ART NO. QTY	4
Included in repair kit 2738	1 · Turbine housing 1 · Rotor unit 1 · Turbine rotor 1 · Compressor wheel		1
Included in repair kit 2738	1 · Rotor unit 1 · Turbine rotor 1 · Compressor wheel		
Included in repair kit 2738	4 1 · · Turbine rotor 5 1 · · Compressor wheel		2
Included in repair kit 2738	5 1 · · Compressor wheel		3
Included in repair kit 2738			4
Included in repair kit 2738	5 I I I I I I I I I I I I I I I I I I		
Included in repair kit 2738	7 1 · · End plate		7
Included in repair kit 2738			8
Included in repair kit 2738	9 4 · · Washer		9
Included in repair kit 2738			10
Included in repair kit 2738			11
Included in repair kit 2738			12
Included in repair kit 2738	3 1 · · Collar	1	13
Included in repair kit 2738	4 1 · · Thrust bearing		14
Included in repair kit 2738	5 3 · · Screw	3	15
Included in repair kit 2738	6 2 · · Bearing		16
Included in repair kit 2738 Included in repair kit 2738		3	17
Included in repair kit 2738 Included in repair kit 2738	8 1 · · Bearing housing	1	18
Included in repair kit 2738 Included in repair kit 2738	9 1 · · Heat shield	1	19
Included in repair kit 2738	0 1 · · Piston ring		20
·	1 8 · Screw		21
Included in repair kit 2738			22
Included in repair kit 2738			23
			24
			25
			26
			27
			28
	9		29 30

7738460 - 25 - 2107 15914 Upd: 2006-11-24