




# Parts Catalog - Option Detail

Electronic Parts Catalog - Option Detail				
Option	Group	Graphic	Film Card	Date
BR9039-04	03.02	br941ga	Z	09-AUG-99
<b>Engines</b>	6C8.3, C GAS PLUS CM556, G8.3, G8.3 CM558, GTA8.3 CM558, ISC CM2150, ISC CM554, ISC CM850, ISC8.3 CM2250, ISC8.3 G CM2180 C101, ISL CM2150, ISL CM554, ISL CM850, ISL G CM2180, ISL8.9 CM2150 L110, ISL8.9 CM2880 L112, ISL9 CM2150 SN, ISL9 CM2250, ISL9 CM2350 L101, ISL9 CM2350 L111, ISLE4 CM850, L GAS PLUS CM556, L8.9, L8.9 L121, L8.9G CMOH2.0 L125B, L9 CM2350 L116B, L9 CM2350 L119B, L9 CM2350 L120C, L9 CM2350 L123B, L9.3 L105, L9.5 L117, L9N CM2380 L124B, QSC8.3 CM2250, QSC8.3 CM2880 C102, QSC8.3 CM554, QSC8.3 CM850(CM2850), QSL9 CM2250, QSL9 CM2250 L115, QSL9 CM2350 L102, QSL9 CM2350 L107, QSL9 CM2350 L118, QSL9 CM2350 L122, QSL9 CM554, QSL9 CM850(CM2850), QSL9 G CM558, QSL9 M CM2250 L106, QSL9.3 CM2880 L113			

©Cummins Inc



SMALL | MEDIUM | LARGE

Cart	Ref No	Part Number	Part Description	Required	Remarks
<a href="#">View My Cart</a>					
		BR9039-04	Crankcase Breather		MR - BREATHER, CRANKCASE...(More)

					Breather Type: Open
					Breather Vent Tube End
					Location: Rear of Engine
					Breather Vent Location:
					Between 3 & 4
					Unique Characteristics:
					Parallel to Crank Centerline
					Rearward
					Engine Family: C Series
					Engine Aspiration:
					Turbocharged; Sea Water
					Aftercooled
					A Compatible Air Cleaner
					System Designed for Closed
					Crankcase Ventilation is
					Required for a Complete
					Closed Crankcase Ventilation
					System
<input type="checkbox"/>	1	<a href="#">202888</a>	Clip	2	
<input type="checkbox"/>	2	<a href="#">3866727</a>	Breather Tube	1	
<input type="checkbox"/>	3	<a href="#">3936331</a>	Rectangular Ring Seal	1	
<input type="checkbox"/>	4	<a href="#">3912072</a>	Self Tapping Metal Screw	2	M8 x 1.25 x 15
<input type="checkbox"/>	5	<a href="#">3937613</a>	Hose Clamp	2	
<input type="checkbox"/>	6	<a href="#">3918611</a>	Plain Hose	1	
<input type="checkbox"/>	7	<a href="#">3935113</a>	Vent Connection	1	Service With 3934865 Seal